

SECRET

1	2
2	3
3	4
4	5
5	6
6	7
7	8
8	9
9	10
10	11
11	12
12	13
13	14
14	15
15	16

TO :
FROM :
ACTION:
INFO :

IN: 91946

085102

TO SECRET 260810Z CITE [REDACTED] 1379

ONE 25X1A
25X1A
25X1A
25X1A

- A. C-216-C
- B. 385
- C. 26 NOV 66 FOR 4 PLUS 05
- D. HQ DIR 3, 6, 9B, 12B, 13C, O/S, STANDARD TRACKER, B-2, R/J
- E. 1. SYS 13C OVERHEAT LIGHT CAM ON 2 PLUS 30 AFTER
T/O AND REMAINED ON UNTIL DESCENT.
2. CABIN TEMP CONTROL GIVES SLOW RESPONSE IN AUTO
AND MANUAL.

F. NEGATIVE
G. NEGATIVE

SECRET TOR: 26/0916Z NOV 66

SECRET

GROUP 1
EXCLUDED FROM AUTOMATIC
DOWNGRADING AND
DECLASSIFICATION